

4DHO Turntable Setup and Operation

Part 1: Calibrating the Bridge

1. Place the Bridge on its mount. (The Walthers/Heljan “Blue Box” will automatically say “**ERR1**” in red text)
2. Press the **red** down arrow function key on the blue box until you get the word “**CAL**” on the display, which means Calibrate.
3. Hit the go/set function key on the blue box to begin the calibration process (when the bridge stops at the calibration sensor, that means the calibration is complete)

Part 2: Operating the Bridge

1. Press the **red** down arrow function key on the blue box until you get “**Tr 1**” on the display.
2. Hit the go/set function key **once**.
3. Using the up or down function keys on the blue box, select the track you want in the servicing facility, then hit the go/set function key again, again only once.
4. Turntable Moves! (Note: If by any chance there is a short/power disruption or the turntable bridge is removed to clean the pit, then the bridge must be recalibrated from the start)